

VIN: VF32220B212280150

PR: 7514

⑥

Expert

66030 2002-12-29 Service - oil + filter change 15w40 £5 + £5
 new rear bushes
 auto fluid ~~check~~ top-up
 washer bottle top-up
 clean oil of engine & power steering
 check everything.

May 2003 - start conversion

June 2003 - Central locking fitting £25 - £35 + £10 + £10

May 2003 - Riddon rear bike rack. ALI £7 + £5
 OPS £2

Welding

Wiring £26

June 2003 - fitted solar vent £35
 fitted table mount

July/Aug Carpeting
 Internal light. (rear)
 New numberplate
 Insulation
 Roof panel
 Gutter

6x ~~old~~ ~~new~~ plug bushes (4.50)

72325 2003-11-17 Service. change coolant £11
 All filter £8
 Fuel filter £7
 Oil filter + change £6 + £5 = £11
 72956 2003-12-26 Bleed Brakes £27 (fluid)
 Replace glow plug #2 (from CIS)
 Tip missing from old one!

7

73495 2004-02-15

7553 2004-02-29

2004-05-03

05-09

05-18

79288 2004-10-22

79356 2004-11-15

79674 2004-12-26

79840 2005-06-02

81376 2005-08-09

80800 2005-09-03

81376 2005-09-17

Timing belt 18

Crackshaft oil seal (7-bolt end) 10-86

Fitted snail chain £1 (bolts)

Repaired wire sheathing under battery

Used soda on belt + terminals

Installed compactment battery

More hot water spritz tank to under bonnet

Built 2 pit battery holders

Adjust tracking - rear side lengthened 1 turn of thread.

Service - oil + filter

Top up from decaying & since used.

Battery charged - put 2000 on in.

Swap starter with one from inside CIS

Add Alarm speaker with little switch

Fix horn

Remove cylinder head - snail chamber

Lather out 1 Engine - £250

Engine removed. Turbo - £100

Chassis painted. Pip + intercooler - £140

New gear mechanism Paint £30

Gaskets etc.

Added Trailer wiring Mount:

Cabling:

Silvered Windows £13

Vinyl floor + wheel arch. £7

Finished carpeting, Fitted Tonten £6

Front Cuff-in, Finished curtains. £

Oil + filter change £9

Swapped both thermo sensors

93436	2006-01-13	New Battery	£75
83446	2006-01-16	New Tyre (Front NS)	£48.18
		MOT. - fixed <i>paint on water pipe above gearbox</i> £45	
	2006-01-21	Washed! Painted wiper base	
88463	2006-07-08	2 rear exhaust sections (broke)	£50
		Worked on new mounts	
	"	Steering rack replaced + leaks, rags.	£65 + £20
		Old rack internal cab bent.	
	2006-08-01	ATX filter	£4
		Oil filter	£5 + £6
		ATX fluid	£5
	?	Fixed belt changer system	
	2007-02	Re-welded Towbar (it broke!)	£0
93504	2007-08-29	Oil Change, tighten sunn plug	£7
		Clean out windscreen wipers ^{re-hill} 45 mins	
	2007-09-	Replaced shiny door handle	£14.86
97600	2007-11-10	Service ... oil filter	£13
		Cleaned out squinters (back/front)	
		Replaced NS sidelamp + NS mirror/side lamp	£11.12
		+ bright pieces (1-12)	
		Topped up battery	£0.69
		Fixed central locking - passenger door	£0.
101,489	2008-04-18	New front R tyre. Michelin more save	£65 ^{thru}
		Tracing adjusted (frontal tyre, arm)	£22.50 ^{thru}
99,800	2008-03-25	New Tyre and end. Front R.	£8.95 ^{thru}
		Servo disk made. wind up to end	£0 ^{thru}
		Central locking not actually fixed (rem disconnected) for key	
100,700	2008-04-01	Central locking finally fixed (added with wires)	£0 ^{2 hrs}
	2008-04-13	Checked brake pads/disks: R drive: 18.8mm. At rest 18mm	
		L drive: 18.5mm	

(105,000	2008-08)	Replace Fuel Filter	£7
	2008-05-17?	Fixed using Bishfield.	£5
	2008-05	Painted cab floor.	
	2008-05-02	Oil change + filter change	£8.96
	2008-12-06	Oil change (3L) 106887	£7
	2009-01-01	Replace Wipers	£8
	2009-03-31	Declared Mileage 108942	
	2009-06-	Dried out cab floor.	£500
	2009-02	MOT + New windscreen, New tyre, New exhaust hse (rem)	£
	2009-09-05 110,800	Oil + filter change	£8
		New brake discs front, (in £45 + 19)	£470 + £
		Service - Bath, washer, coolant. Bleed Front brakes	
		(new nipple sized)	
		Air filter	£6
	2010-1-17	New door for Ford (Stainless).	£50
	02-18	MOT check	£55
	2010-08-22	Replaced Front Rear Brake (cylinder) + spacer	£319. £26?
		Replaced driving wiper.	£5
	116138 2010-09-04	Service: (115,000) Change Brake fluid.	
	108,000 2010-09-11	Change Coolant	
	"	Replace 2 glow plugs (12mm long, sorted)	£2.70
	"	Change Oil + Filter	
	2010-11-21	2011-April-on- Front off-side puncture fix	£21
	110670 2010-10-22	Change Fuel filter (old one dosed)	£6
	122124 2011-11-18	Not starting reliably - fit intermediate starter motor relay	£0.
	123280 2012-02-23	Replace windscreen wipers	£83
	2012-4-14	Front nearside puncture/valve fix	£21.
	133170? 2012-05-26	Oil change	£15
	127363 2012-10-21	Fuel Filter	£4
	"	Glow plug	£5?

Expert Van pt 2

127363 2012-10-12 New AGM Battery £135
 New Earth cable.
 (Cleared water out of Inj Pump (clogged))
 Budget starter switch.

2013-03-29 Removed Fuel Tank & drained Munk
 Painted Fuel frame - repaired hole in protector.

2013-05-25 Rear Brake shoes replaced £30?

2013-06-27 De-rusted spare disc & supplied (Front new one)
 Purchased one from last year

1007 → Painted rear brake pipes. Replaced Wiper Blades

2013-06-30 Added Aux Batt wires to Van. - Air Filter?
 + Used Power LED to fridge.

129000 2013-07 Skinned spare discs distribution £30
 Fitted Aux batt fuse box + selector switch.

Power to fridge, USB sockets, Radio, Inverter £10

Fitted inverter + USB sockets. £4

~~Replaced~~ Voltmeter for Aux batts £6

Sold hard central locking. -

Replaced oil (+ filter) £15

- Cab floor dry (leakscreen fixed it)

132163 2013-09-01 New timing belt £16

Replaced tensioner with one for old engine

New idler pulley £31.15

New Crankshaft oil seal.

New crankshaft bolt £4.54

Replaced Coolant antipump £15.50

Changed oil £12

2013-09-25 New lower engine mount bush £15.50

Changed gear box oil (Comau 9AE75W/80) £13

Vivaro

Revised

Van p.2

135,660 2015-07-25 Seal off RH side Brake Disc for MOT
Leads (oil, Screen)
Clamp loose pump-steering pipe to frame.
Change LH track rod end (not new)

137,000 2015-11-01 Clean sganters

138,080 2015-06-13 End Filter

Oil Filter, + oil

Replaced long wiper blade

Coolant 2cm down - topped up.

Clean oil off car cover. Sealant on central bolt.

Screenwash top up

Replaced front brake hoses L&R

Replaced front brake pipe LHS

Replaced Rear RHS brake pipe.

Fettled caliper RHS

Put skimmed Disc on RHS

Painted (under coat) Rear RHS trailing arm

Re New type Rear LHS Roadstone Blue E10 'B' £38 x 13

Replaced Horn. Painted WS. Batt frame.

142,385 2015-09-06 oil top up

Replaced offside shiving door handle

Tightened grille on back over car cover (oil leak?)

2016-06-26 Swapped batt (Not from standing)

2016-08-20 Swapped batt back.

Replaced front L headlamps bulbs.

Cleaned Tets. Replaced LH Tied/155

2017-05-08 Handled gear box & Tets thoroughly

2017-06-22 Do - final check

2017-08-06 Freed-up rear door lock (good)

Fixed (in better shape)

Van

6,000 (10,000) Servicing

Oil (+ Filter)

66,000 2002-12

72,000 2003-11

79,000 2004-10

81,000 2005-09

88,000 2006-07

93,500 2007-06

97,600 2007-11

105,000 2008-05

107,000 2008-12

110,800 2009-09

116,000 2010-09

123,000 2012-10

129,000 2013-07

132,000 2013-09

138,000 2015-06

148,000 2017-07

154,000 2018-10

164,000 2022-04

Air Filter

72,000 2003-11

88,500 2006-07

110,000 2009-09

132,000 2013-09

148,000 2017-08

164,000 2022-04

Fuel Filter

72,000 2003-11

105,000

117,700 2010-10

127,000 2012-10

138,000 2015-08

150,000 2018-06

164,500 2022-06

Coolant

72,000 2003-11

116,000 2010-09

132,000 2013-09

148,000 2017-08

164,500 2022-06

Gear box Oil

132,000 2013-09

36,000/2yrs (1yr)

Brake Fluid

73,000 2003-12

116,000 2010-09

148,000 2017-09

157,000 2019-07

158,000 2021-05

£2,000 (72,000)

Timing Belt

73,000 2004-02

79,700 2006-12

132,000 2013-09

Expend Van pt 3

Van pt 3

2017-05-06 ~~Oil and new brake components~~

2017-05-09 LH wiper ~~replaced~~ replaced. £14.90

2017-05-24-27 Painted subframe (new) (£60) £20
7 shocks, springs, hubs

Adjusted Brake compensator safety

2017-05-13 Tighten Fan belt

2017-07-22 Replace offside steering gaiter £19
Bleed brake brakes

Change passenger seat to fixed.

07-27 MOT rear brakes 33% imbalance (low offside). (£54)

2017-07-29 Clean offside sliding door ^{lock} (longer door)

147,800 2017-08-18 Fit retainers O/S wheel arch plastic £6

2017-09-23 Painted primer on motorhome windows

148,400 2017-09-16 Replace brake fluid (old fluid...) £7

2018-04-20 Fit new steering £50

2018-06-02 Replace Fuel Filter £500

Lower Passenger seat metal frame

2018-06-24 Replace rear offside brake cylinder £18

Paint rear wheels (£18 each) £30

(Pending!) 06-30 Replace rear-side brake suspension arm (both degraded) £29

07-07 Paint front wheels -

Free slide OSF, Adjust handbrake balance

07-14 Replace Caliper sliders £2749

07-11 MOT (OSF sticking, rear brake (compensator) valve) £55

2018-07-21 New brake slider OSF - £27 (12)

Change OSF kits + discs (spindles and discs, all parts)

155,000 2018-10 Tighten Fan belt

Fit Hawk King Range. £30

Fix leaks - silicone Apical, using drain

braked wiper grill.

156,974 2019-07-11 Replace long wiper £2 ~~£29~~ £29

Replace offside suspension arm (gaiter split)

Repair offside caliper: new slider, bar, ^{clip} bolts

Replace rear compensator £54 £21/2 £18 (12)

Brake / hand

Garage adjusted compensator £25

2020-06-12 Replace both front wheel bearings £12 + £12 + £60

Replace nearside suspension arm £29

Removed leisure battery

Removed internal light above door.

2021-04-01 Convert glow plugs to button. (1)

Test master cylinder (OK)

Bleed brakes all £7

159,169 2021-08-04 New front discs + pads £46

New bleed nipples for nearside £7 (11 pairs)

Adjust rear compensator (nearside bar)

MOT ✓ £55

2021-11-01 Battery (Targa) 067TE £66

163,674 2022-04-10 Corrected Tracking. (£35 (driving)) £77 (correcting)

from 1° to 0° 8' 30" ± 4' 15" WS'

04-17 Oil filter change. £20?

Air filter change £7

Inner side of slide discards - cleaned.

04-23 2 New Front Tyres Nexen Pro £124 + £25

Onion CV boot LH side replaced £39.64

L4 drive shaft oil seal replaced £1

04-27 MOT £54

06-16 New coolant, New Fuel Filter £17 + £5?

Added 2nd fan. - (Ex (15)

Replaced thermostat + seals. £7

153
154
155

2022-07-10
2022-07-15

logbook 11067926

Van

2022-07-10 Wiper in 2nd Fan
2022-07-15 Replaced Blower fan (4pin version!) \$33.14
2022-09-15 Replaced Glass scan - Remote control (S. Kuddus) - 15
2022-04-17 New wiper ^{rubber} blades both sides ~\$9
2022-11-17 New dash cover + trap stop on struts \$26
2022-11-17 Handcut of strut + spring
169-472 2022-07-16 28" wiper rubber fitted - New wiper \$0
07-10 Gooped top side scan (fixed). Stopped Leak! \$0
07-23 Replaced fan AIS Central Locking \$0
wiggled indicator / master unit. No work \$0