
SOAKAWAY
DRAIN TO SOAKAWAY
NEW 68MM DIA PWP
New 3G window
TIMBER POST 100mm SQ
New 3G french doors
FLUSH THRESHOLD TO GARDEN
FLAT CEILING
NEW SUN ROOM
NEW GLULAM BEAM TO STRUCTURAL ENGINEERS DETAILS
EXISTING WINDOW RETAINED
EXISTING BRICKWORK WET PLASTERED
VAULTED CEILING
NEW VELUX WINDOW
STORE
NEW DOORS TO STORE & WORKSHOP WITH LINTELS OVER
DOOR FROM LIVING TO BE PROVIDED TO STORE & WORKSHOP
VAULTED CEILING
EXTG PWP REMOVED
NEW WORKSHOP
NEW VELUX WINDOWS OVERHEAD
EXISTING DOOR REPLACE WITH NEW INSULATED ELECTRICAL GARAGE DOOR
EXISTING SURFACE WATER MANHOLE
EXTG PWP
EXTG PWP
EXISTING EXTERNAL DOOR RETAINED
STEP DOWN TO NEW EXTENSION
DINING AREA
LIVING ROOM
DENOTES ANGLES IN CEILING
BRICKWORK WALL BUILT UP TO TOP OF KNEE WALL TO CLOSE VAULTED CEILING
CUPD
CUPD
KITCHEN
HALL
NEW SECTION OF KITCHEN WORKTOP
EXISTING SVP RELOCATED
CUPD
CLOAK
EXISTING EXTERNAL DOOR TO GARDEN
New 2G/3G entrance door
NEW 68MM DIA PWP
NEW RWP
NEW 68MM DIA RWP
EXTG GULLY
EXTG GULLY
EXTG TRAP
EXISTING FOUL MANHOLE
NEW FOUL DRAINAGE CONNECTION FROM NEW SVP/POSITION
EXISTING FOUL MANHOLE
EXISTING SURFACE WATER DRAIN CONNECTION RETAINED
DISRUPTED LINES OF EXISTING DRAIN RUNS
N
METRES
0
1
2